If you are using a printed copy of this procedure, and not the on-screen version, then you <u>MUST</u> make sure the dates at the bottom of the printed copy and the on-screen version match.

The on-screen version of the Collider-Accelerator Department Procedure is the Official Version.

Hard copies of all signed, official, C-A Operating Procedures are kept on file in the C-A ESHQ

Training Office, Bldg. 911A.

C-A OPERATIONS PROCEDURES MANUAL

4.120.8 Access Control – Annual Acceptance Tests for 8 O'Clock

Text Page 2

Hand Processed Changes

Date

Page Nos.

 		 _
 		 _
 		 _
 		 _
	G	
Approved: <u>Signature on File</u> Collider-Accelerator Department Chairm		- Date

V. Castillo

HPC No.

Initials

Annual Acceptance Tests for 8 O'Clock

1. Purpose

The purpose of this procedure is to define the Annual Acceptance tests for 8 O'clock.

2. Responsibilities

2.1 Refer to C-A OPM 4.120, "Access Control Acceptance Tests".

3. <u>Prerequisites</u>

- 3.1 Refer to C-A OPM 4.120, "Access Control Acceptance Tests".
- 3.2 C-A OPM 4.120 must be understood before conducting the tests described in this Procedure.

4. **Precautions**

4.1 Refer to C-A OPM 4.120, "Access Control Acceptance Tests".

5. <u>Procedure</u>

5.1 Perform the tests described in Attachments 8.1 - 8.9.

6. Documentation

6.1 Refer to C-A OPM 4.120, "Access Control Acceptance Tests".

7. References

7.1 Refer to C-A OPM 4.120, "Access Control Acceptance Tests".

8. Attachments

- 8.1 C-A OPM ATT 4.120.8.a, Critical Device Tests.
- 8.2 C-A OPM ATT 4.120.8.b, Gate Tests.
- 8.3 C-A OPM ATT 4.120.8.c, Crash Operator Tests.
- 8.4 C-A OPM ATT 4.120.8.d, Sweep Tests.
- 8.5 C-A OPM ATT 4.120.8.e, Mode 24 Tests.
- 8.6 C-A OPM ATT 4.120.8.f, Chipmunk Tests.
- 8.7 C-A OPM ATT 4.120.8.g, Power-Up Tests.
- 8.8 C-A-OPM-ATT 4.120.8.h, Oxygen Deficiency Hazard (ODH) Tests.
- 8.9 C-A-OPM-ATT 4.120.8.i, PHENIX Gas Detection Tests.